



Servo 0:
Rotating base

Servo 1:
Shoulder

Servo2:
First elbow

Servo 3:
Second elbow

Servo 4:
Wrist

Servo 5:
Hand (Gripper)

Step down converter:
Input: 12 Vdc. 6.0A
Output: 6 Vdc. 6.0A

Power supply:
Gacun-1260
Input: 110-240V
Output: 12Vdc. 6.0A