

Action	Object	Change Document	Status
Add Components			
Add	C102	To cahrgebot_digital.PcbDoc	Footprint Not Found CAP_0603
Add	C103	To cahrgebot_digital.PcbDoc	Footprint Not Found CAPC1608X9
Add	C105	To cahrgebot_digital.PcbDoc	Footprint Not Found CAPC1608X9
Add	C107	To cahrgebot_digital.PcbDoc	Footprint Not Found CAPC1608X9
Add	C200	To cahrgebot_digital.PcbDoc	Footprint Not Found EEETC1V470
Add	C201	To cahrgebot_digital.PcbDoc	Footprint Not Found CAPC2012X7
Add	C202	To cahrgebot_digital.PcbDoc	Footprint Not Found CAPAE660X7
Add	C203	To cahrgebot_digital.PcbDoc	Footprint Not Found CAPC2012X7
Add	C402	To cahrgebot_digital.PcbDoc	Footprint Not Found CAPC1608X9
Add	D101	To cahrgebot_digital.PcbDoc	Footprint Not Found LED-0603-BL
Add	D200	To cahrgebot_digital.PcbDoc	Footprint Not Found DIOM5436X2
Add	D201	To cahrgebot_digital.PcbDoc	Footprint Not Found DIOM5436X2
Add	D202	To cahrgebot_digital.PcbDoc	Footprint Not Found LED-0603-BL
Add	D401	To cahrgebot_digital.PcbDoc	Footprint Not Found SOD3816X13
Add	D403	To cahrgebot_digital.PcbDoc	Footprint Not Found SOD3816X13
Add	D404	To cahrgebot_digital.PcbDoc	Footprint Not Found SOD3816X13
Add	J401	To cahrgebot_digital.PcbDoc	Footprint Not Found SAMTEC_MT
Add	Q300	To cahrgebot_digital.PcbDoc	Footprint Not Found SOT96P237X
Add	R104	To cahrgebot_digital.PcbDoc	Footprint Not Found RESC6331X7
Add	R105	To cahrgebot_digital.PcbDoc	Footprint Not Found RESC6331X7
Add	R106	To cahrgebot_digital.PcbDoc	Footprint Not Found RESC1608X5
Add	R107	To cahrgebot_digital.PcbDoc	Footprint Not Found RESC6331X7
Add	R108	To cahrgebot_digital.PcbDoc	Footprint Not Found RESC1608X5
Add	R300	To cahrgebot_digital.PcbDoc	Footprint Not Found RESC1607X6
Add	R302	To cahrgebot_digital.PcbDoc	Footprint Not Found RESC1607X6
Add	R402	To cahrgebot_digital.PcbDoc	Footprint Not Found RESC1608X5
Add	RV200	To cahrgebot_digital.PcbDoc	Footprint Not Found S14K300

Action	Object	Change Document	Status
Add Pins To Nets			
Add	C102-1 to 3.3V_AFE	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C102-1
Add	C102-2 to GND	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C102-2
Add	C103-1 to N	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C103-1
Add	C103-2 to NetC103_2	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C103-2
Add	C105-1 to V+	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C105-1
Add	C105-2 to N	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C105-2
Add	C107-1 to N	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C107-1
Add	C107-2 to V-	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C107-2
Add	C200-1 to +12	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C200-1
Add	C200-2 to GND	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C200-2
Add	C201-1 to +12	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C201-1
Add	C201-2 to GND	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C201-2
Add	C202-1 to +5	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C202-1
Add	C202-2 to GND	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C202-2
Add	C203-1 to +5	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C203-1
Add	C203-2 to GND	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C203-2
Add	C402-1 to I1-	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C402-1
Add	C402-2 to GND	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin C402-2
Add	D101-1 to NetD101_1	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin D101-1
Add	D101-2 to GND	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin D101-2
Add	D200-1 to +12	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin D200-1
Add	D200-2 to GND	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin D200-2
Add	D201-1 to +5	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin D201-1
Add	D201-2 to GND	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin D201-2
Add	D202-1 to NetD202_1	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin D202-1
Add	D202-2 to GND	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin D202-2
Add	D401-1 to NetD400_2	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin D401-1
Add	D401-2 to N	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin D401-2
Add	D403-1 to 3.3V_AFE	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin D403-1
Add	D403-2 to NetD402_2	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin D403-2
Add	D404-1 to NetD402_2	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin D404-1
Add	D404-2 to N	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin D404-2
Add	J401-01 to NetFL401_2	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin J401-01
Add	J401-02 to N	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin J401-02
Add	M200-6 to GND	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin M200-6
Add	Q300-1 to NetQ300_1	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin Q300-1
Add	Q300-2 to 3.3v	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin Q300-2
Add	Q300-3 to NetQ300_3	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin Q300-3
Add	R104-1 to NetR103_2	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R104-1
Add	R104-2 to NetR104_2	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R104-2
Add	R105-1 to NetR104_2	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R105-1
Add	R105-2 to NetD102_1	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R105-2
Add	R106-1 to NetD102_1	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R106-1
Add	R106-2 to V+	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R106-2
Add	R107-1 to N	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R107-1
Add	R107-2 to NetD102_1	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R107-2
Add	R108-1 to N	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R108-1
Add	R108-2 to V-	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R108-2
Add	R300-1 to NetR300_1	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R300-1
Add	R300-2 to MCU_TX	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R300-2
Add	R302-1 to AFE_TX	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R302-1
Add	R302-2 to NetR302_2	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R302-2
Add	R402-1 to I1-	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R402-1
Add	R402-2 to NetFL401_2	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin R402-2
Add	RV200-1 to NetF200_2	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin RV200-1
Add	RV200-2 to NetM200_3	In cahrgebot_digital.PcbDoc	Unknown Pin: Pin RV200-2

Action	Object	Change Document	Status
Add Component Class Members			
Add	C102 to AFE	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	C103 to AFE	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	C105 to AFE	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	C107 to AFE	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	C200 to power1	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	C201 to power1	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	C202 to power1	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	C203 to power1	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	C402 to ct_interface	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	D101 to AFE	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	D200 to power1	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	D201 to power1	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	D202 to power1	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	D401 to ct_interface	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	D403 to ct_interface	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	D404 to ct_interface	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	J401 to ct_interface	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	Q300 to interface1	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	R104 to AFE	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	R105 to AFE	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	R106 to AFE	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	R107 to AFE	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	R108 to AFE	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	R300 to interface1	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	R302 to interface1	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	R402 to ct_interface	In cahrgebot_digital.PcbDoc	Failed to add class member : Com
Add	RV200 to power1	In cahrgebot_digital.PcbDoc	Failed to add class member : Com