



Decode A0-2
combine 0+1 for USB
use 2 for KBD in and out
ignore 3
and combine 4+5 for LCD

Decode A1-3
Ports treated in pairs
0-1 = USB
2-3 = KBD
4-5 = LCD
A0 is used on BeanZee to select data/status
A0 is used here to select data/status for LCD
KBD ignores A0



Sheet: /
File: PortDecoding.kicad_sch

Title:

Size: A4
KiCad E.D.A. kicad 7.0.10

Date:

Rev:

Id: 1/1