



TODO: Resistor ??? < 200 ohms according to spec <https://electronics.stackexchange.com/questions/123172/what-is-the-ideal-way->



TODO: Add SATA power connector



TODO: Should I connect the screw holes to ground? - <https://superuser.com/questions/1138512/what-exactly-is-grounded-through-motherboard-standoffs>

Screw holes matching those on a ATX motherboard. So the board can be secured to a motherboard standoff or cable-tied to the caseSee https://en.wikipedia.org/wiki/Computer_case_screws#Motherboard

Mounting hole ##6-32 UNC Mounting hole ##6-32 UNC

