


H1
MountingHole


H4
MountingHole




H2
MountingHole

H3
MountingHole


Power Input
Screw Terminal 5V @ 10A+




Strobe Input
3-pin 100mil




Strobe Output
Screw Terminal 15-42V @ 2.3-3.75A




LED Strip (Optional)
USB-A 5V




Raspberry Pi5 Power Only
USB-C 5V @ 5A




Raspberry Pi5 Power Only
USB-C 5V @ 5A



Strobe Duty Cycle Limiter



15 - 42V Boost Converter @ 100mA



Adjustable Constant Current Sink

