

## SYSTEM ISSUE REPORT

System Name : Lasys  
Version : 101.22

Issue No. : 20-ICS-017  
System User : Laarni C. Lubiano *07/21/20*

Device Name : CSO09

Date encountered : July 21, 2020

Problem :

During preparation of LMI, PIC encountered abnormality in barcode.

Normally, barcode is color black however during preview prior printing code is color red.

### To be filled-out by troubleshooting PIC

Received By : J. Maderazo *07/21/20*

Received date : 07/21/20

Findings :

LMI/Instruction Barcode (.bl) file was not updated in the client PC.

This was also already reported / encountered (refer to 19-ICS-014) and resolved by the INDRA Team.

Action Taken :

Get the updated file in BX54 and copy it to the CSO09 (location: C:\LASYS\opt1)

Resolved Date : 07/21/20  
Troubleshooting PIC : *[Signature]* 07/21/20  
Name & Signature

Troubleshooting Manager : *[Signature]* 07/21/20  
Name & Signature

### To be filled-out by Requestor (after completion of request)

Confirmed by: \_\_\_\_\_  
Name & Signature

Remarks: \_\_\_\_\_



### INFORMATION

Sample

Lot No.	Previous Balance	Receive	Usage		Loss	Return	Balance
			Actual	Sample			

FM-750-7501G

SPS-020 rev.1

07/21/2020

Issued by PPS

Signature :



(01)14806017509283(17)250731(10)200805A0(99)SG328G03L2138WB

## LASER MARKING INSTRUCTION

### INFORMATION

Item Code : SG3+03L2138

Laser Marking Item Code: SG329G03L2138WB

Lot No. : 200805A

Barcode No. : (01) 14806017509283 (17) 250731 (10) 200805A

Printed Top Web Item Code: SG328G03L2138WB

Sample

Lot No.	Previous Balance	Receive	Usage		Loss	Return	Balance
			Actual	Sample			

PREPARED BY :

CHECKED BY :

VERIFIED BY :