

UART3 Rx
UART3 Tx
+12V switched


+ 5V
Motor Hall A
Motor Hall B
Motor Hall C
GND

GND
UART1 Tx
Power button
+5V

GND
SWCLK
SWDIO

3.3V

Battery -
Battery +





- Battery +

GND
 UART1 Tx
 Power button
 +5V



3.3V

