



1.1.0-1 (2021-05-17):

- PCB re-design for single side component placement,
- replace micro USB connector by another THT type,
- replace ISP-6 programmer connector by Pogo-pin contacts,
- replace XH2.54 connectors from SMD to THT variants,
- replace switched-mode power supply (+5V).