



Note TEXT crossed over to RINT between the two chips. This effectively bridges the two transceivers.

In the interest of minimizing board size, there is no ESD suppression on the CAN or power lines, and there are no CAN chokes to keep board noise down.

Title		
Size	Number	Revision
A		
Date:	11/4/2015	Sheet of
File:	Z:\russery On My Mac\...can_bridge.SchDoc	Drawn By:





