



3 Screw terminals, 1 screw terminal will be for the 12V Battery in and the other 2 will be for 12V out. One 12V out will power the motor controller, and the other will be for anything else



3 Buck converters, in v2 all the power modules are going on the same board. This means we will need wide traces in the PCB.

Sheet: /
File: Power Module.sch

Title:

Size: A4
KiCad E.D.A. kicad (5.1.4)-1

Date:

Rev:
Id: 1/1