

INIT I2C

CONECT
HTU21DREAD
TEMPERATURE

READ HUMIDITY

SALIDA

CALL

NO-CALL

NO-CONNECT

CONNECT

TEMP < -45°C

TEMP > 125°C

-45°C<TEMP < 125°C

HUM < 0%

HUM>100%

0%<HUM<100%

INIT_I2C_OK

INIT_I2C_NOK

COM_HTU21D_OK

COM_HTU21D_NOK

0xFF

TEMP

HUM

1
2
3
4
5
6
7
8
9
10