


Tachometer signal will be on this pin if the fan provides it. Measuring that signal on an oscilloscope I found that it produced voltage spikes of around 20V which would hurt the pico so I did not use this signal.



Devon Bray Aftermarket cooler for NVidia Tesla GPUs Drives six fans on two coolers for two GPUs, cooler A and cooler B Controlled by Raspberry Pi Pico www.esologic.com/testa_cooler		
Sheet: / File: tesla_cooler.sch		
Title: Tesla Cooler		
Size: A4	Date: 2021-10-03	Rev: 1
KiCad E.D.A. eeschema 5.1.9-73d0e3b20d88ubuntu18.04.1		Id: 1/1