



















Unused GPIO pins are pulled to ground via 10k resistors, and should be left set to inputs.



TITLE: Turaco: CPU		REV: 0.3A
	Company: Studio 8502	Sheet:
	Date: 2023-04-29	Drawn By: Kyle J Cardoza















TITLE: Turaco: Video Controller		REV: 0.3A
	Company: Studio 8502	Sheet:
	Date: 2023-04-29	Drawn By: Kyle J Cardoza








TITLE: Turaco: Audio		REV: 0.3A
	Company: Studio 8502	Sheet:
	Date: 2023-04-29	Drawn By: Kyle J Cardoza



TITLE: RTC		REV: 0.3A
	Company: Studio 8502	Sheet:
	Date: 2023-05-05	Drawn By: Kyle J Cardoza







TITLE: Turaco: Power Supply		REV: 0.3A
	Company: Studio 8502	Sheet:
	Date: 2023-04-29	Drawn By: Kyle J Cardoza