


2

1

Enclosed No. 25 chain to be placed around the 80 tooth sprocket, a sprocket on the motors drive shaft, and a sprocket on the encoder. The tensioner is to be pressed against the chain to reduce slack.

Motor rear






Encoder slot

Driver shaft slot

Motor slot

Driving chain tensioner

80 tooth sprocket



2

1