


The first diagram shows the J3 header connections. It is a 10-pin header with pins numbered 1 to 10. Pin 1 is connected to GND. Pin 2 is connected to +3V3. Pin 3 is connected to GPIO48. Pin 4 is connected to GPIO47. Pin 5 is connected to GPIO21. Pin 6 is connected to GPIO14. Pin 7 is connected to GPIO13. Pin 8 is connected to GPIO12. Pin 9 is connected to +3V3. Pin 10 is connected to GND. The header is labeled J3 Ext.

The second diagram shows the J4 header connections. It is a 4-pin header with pins numbered 1 to 4. Pin 1 is connected to GND. Pin 2 is connected to +3V3. Pin 3 is connected to RX. Pin 4 is connected to TX. The header is labeled J4 UART.



- H1 MountingHole
- H2 MountingHole
- H3 MountingHole
- H4 MountingHole
- H5 MountingHole

