



SW123 and SW124-2 were accidentally swapped in the physical PCB layout. The firmware will be changed to reflect this.

Key Matrix




RGB LED stuff





Microprocessor Bypass caps

Microcontroller



Reset circuit

Hotswap standoff holes



Logos, holes, misc.