



## 02.09.2025 - After roof work



by KE8TJE

- New coax was installed on Friday. With a RF chork installed as per the manual
- Traps were fixed. They had a crack and a disconnected connection



20 m









10 m



15 m



# CL-33-M



**\*The name "Classic", "Mosley Classic", "Classic 33", "CL-33 Classic", "Classic Feed", "Classic Tri-Band Beam", "Classic 3 Band" are all copyrighted or patented names solely belong to Mosley Electronics, Inc. Any use without the express permission of M.E.I. is prohibited.**