



USB connector and 3V3 regulator




Nixie power supply




Currently the efficiency is ~80%, which is not enough.
IC and transformer must be replaced in REV B


ESP-12F module




RTC




Nixie drivers



USB to serial converter



Mechanical



Nixie Board module pads

NIXIE TAP
REV A MLADEN DINIC 2018

