



GENERAL NOTES		
The 4 M3X0.5 bolts may differ depending on the available HW.		
Gamma match material must be copper to ensure weldability to the coaxial cable.		
It might be necessary due to RF wizardry to weld the radials to the boom and so threads and cuts might be unnecessary.		

Dept.	Technical reference	Created by Federico	04/06/2023	Approved by
		Document type	Document status	
		Title HB9CV 402MHz	DWG No.	
		Rev.	Date of issue	Sheet 1/1