

This is the PWM driver for the flying robot coil arrays.

We want to drive up to 2A per coil continuously at 12V. So for a four-coil unit, you need 8A per driver at 12V!

