


add divider to FB
resistors and parallell C
if LM3671-ADJ was used.



Alarm Light Main board / Juraj Repcik

Alight_main_board_v3

29-Dec-18 17:48

Sheet: 3/3

Rev:03