







Fix Bus Wire polarity



Capacitor needs to be directly connected to the bus. No Bridge rectifier inbetween!



TC:Bus Intercom Gateway

Sheet: /  
File: doorman.kicad\_sch

**Title: Doorman S3**

Size: A4	Date: 2026-01-07
----------	------------------

Size: A4	
KiCad E.D.A. 9.0.0	

Rev: 1.6.1

Id: 1/1