

If mode is open: Works with zero blanking chaining.
 if Pin 1 is high, display both zeros, and drive pin 10 high
 if Pin 1 is low, zeroes become blank, and if the value is zero on both displays, drive pin 10 low
 If mode is closed: Pin 1 becomes Output Enable.
 when low: only the right dot is turned on to signify power
 when high: display functions normally

