


J1 and J2 select the stepping mode.

- 00 - 1/8 step
- 01 - 1/4 step
- 10 - 1/2 step (w/ torque comp)
- 11 - Full step



TITLE PICStep - Copyright Alan Garfield 2004

FILE: PAGE 1 OF 1 REVISION: V4.0 DRAWN BY: Alan