



6676 Corporate Center Parkway  
Suite 107  
Jacksonville, FL 32216  
Phone: (800) 890-4835  
www.itelinc.com


Attn:  
To:

From: **ITEL Customer Experience Dept.**  
Email: **customerexperience@itelinc.com**

## TILE ROOFING EVALUATION

<b>CUSTOMER INFORMATION</b>		
Customer: <b>ITEL</b>	Control #: <b>F3M5863066</b>	Cust. ID: <b>ITELDEMO0001</b>
Date Rcvd: <b>11/12/2019</b>	Date Inv: <b>11/12/2019</b>	Add Cust: <b></b>
Adjuster: <b>ITEL Appdemo4</b>		Rep: <b></b>
Comments: <b></b>		
<b>INSURED INFORMATION</b>		
Claim #: <b>AS-4684</b>	Loss Date: <b>11/7/2019</b>	
Insured Name: <b>Ian</b>	Area Damaged: <b>TOP</b>	
City,State,Zip: <b>Terre Haute, IN 47809</b>		
Comments: <b></b>		
<b>ORIGINAL PRODUCT</b>		
<b>Brand</b> Auburn Tile	<b>Line</b> Brushed Shake	<b>Color</b> <b></b>
<b>Manufacturer Contact Info:</b> Auburn Tile / www.auburntile.com / (909) 984-2841		
Comments: <b></b>		
<b>SIMILAR MATCH(ES)</b>		
<b>*Similarity Rating</b>	<b>Brand</b>	<b>Line</b>
		<b>Color</b>
Comments: <b></b>		
*Similarity Rating: 1- Exact matching profile and lug pattern(candidate for same slope repair), 2- Excellent profile match, slight difference in interlocking mechanism/lug pattern ( candidate for full elevation/slope repair product) 3- Comparable profile match, no suitable repair match found, (This product is not intended as a repair type product, but rather a similar replacement type product for cost analysis.)		
<b>TILE ANALYSIS</b>		
Body Composition: <b>Concrete</b>	Tile Profile: <b>Flat</b>	
Surface Texture: <b>Rough</b>	Surface Texture 2: <b>N/A</b>	
Coloration Method: <b>Oxide Thru Body</b>	Visual: <b>Flashed Blend</b>	
Edge Texture: <b>Rough</b>	Edge Shape: <b>Square</b>	
Valley Type: <b>N/A</b>	Interlocking: <b>Yes</b>	
Width: <b>9.250</b>	Tapered: <b>No</b>	
Height: <b>15.000</b>	Projection Height: <b>0.000</b>	
Comments: <b></b>		
<b>COMMENTS</b>		

## PHOTOS SUBMITTED



Top of Roof Tile



Overall Roof



Back of Roof Tile