






## TEST TCAD







OrCAD Capture CIS - Lite - [/ - (SCHEMATIC1: PAGE1)]

File Design Edit View Tools Place SI Analysis Accessories Options Window Help

cadence

CON4

Start Page testlab.opj PAGE1\* LIBRARY5 LIBRARY5... SCHEMATIC1...

Place Part

Part

CON4

Part List

CON32/CONNECTOR  
CON33A/CONNECTOR  
CON34/CONNECTOR  
CON34A/CONNECTOR  
CON36/CONNECTOR  
CON39/CONNECTOR  
CON4/Design Cache  
CON4/CONNECTOR

Libraries

1\_SHOT  
7400  
744C  
744CT  
744LS  
744S

Packaging

Parts per Pkg: 1

Part:

Type: Homogeneous

Normal Convert

Search for Part

Ready

0 items selected

Scale=100% X=8.70 Y=3.60

7:47 PM 25-Nov-21

OrCAD Capture CIS - Lite - [/ - (SCHEMATIC1: PAGE1)]

File Design Edit View Tools Place SI Analysis Accessories Options Window Help

cadence

NPN BCE

Start Page testlab.opj PAGE1\* LIBRARY5 LIBRARY5... SCHEMATIC1... bloc\*

Place Part

Part

NPN BCE

Part List

NPI19H\_B/MISC  
NPI19H\_H/MISC  
NPI19H\_J/MISC  
NPI19V\_A/MISC  
NPI19V\_B/MISC  
NPI19V\_H/MISC  
NPI19V\_J/MISC  
NPN BCE/Design Cache

Libraries

1\_SHOT  
7400  
744C  
744CT  
744LS  
744S

Packaging

Parts per Pkg: 1

Part:

Type: Homogeneous

Normal Convert

Search for Part

Ready

0 items selected

Scale=100% X=7.80 Y=4.90

7:56 PM 25-Nov-21

(7.10, 4.30)

INFO(ORCAP-2282): The following 1 points have been identified as net connectivity change points from the last operation

(7.00, 4.80)

(3.80, 0.90)

INFO(ORCAP-2282): The following 1 points have been identified as net connectivity change points from the last operation

(6.00, 3.70)