



Overview: Extent of the spill incident impact on 28" Bomu-Bonny Pipeline at Bodo West .  
Pictures taken during Joint Investigation of 26<sup>th</sup> February, 2011



Close-up: Spill due to illegally welded points on 28" Bomu- Bonny Pipeline at Bodo West.. Picture taken during Joint Investigation of 27<sup>th</sup> February, 2011.