

WIRING I-PDU A (Switching Lt.2) From UPS A

UPS A (Pengembangan Lt.2)
Fuse Q2-03 (140/200A)

I-PDU A
Switching LT.2

Panel ITX
Fuse 140/200 A

Fuse
140/200A

