



Id: 1/2



use low ESR types for C8 & C7
R12 & R13 need to
about five times the
hot filament resistance

"center tap"
adjust with D2

Filament AC Supply

Id: 2/2