


NOTE: C1 values should be reviewed for each string. C2 placement should be reviewed, maybe a resistor would be better instead

Guitar Pickups



NOTE: Value of R1-R6 should be reviewed.

NOTE: A capacitor between the other two ends of the bridge rectifier (the ones not connected with R1) might further clean the signal

TITLE: String Amplitude detection		REV: 1.0
嘉立创EDA	Company: Your Company	Sheet: 1/1
	Date: 2022-11-10	Drawn By: rjuna