



NOTE: Value of R1-R6 should be reviewed.

NOTE: A capacitor between the other two ends of the bridge rectifier (the ones not connected with R1) might further clean the signal