




(a) SI1000 0.002 Lower is better ↓




(b) SI1000 0.004 Lower is better ↓




(c) SI1000 0.008 Lower is better ↓




(d) Const. 0.002 Lower is better ↓



(e) Const. 0.004 Lower is better ↓



(f) Const. 0.008 Lower is better ↓



—■— Bacon-Shor —★— Color —●— Gross —▲— Heavy-hex —✕— Steane —◆— Surface