



上海恩艾仪器有限公司 中国服务中心  
中国上海市龙东大道3869号2号楼3楼  
201203  
Tel:021-50509800

Page: 1 of 2

OE#: 20724987

Date: 20/05/15

SHIP TO: 2674958-849597

尚文 左

上海季恩仪器有限公司

昆山市经济开发区前进东路399号台协大厦1803室

昆山 - 经济技术开发区 215300

China

BILL TO: 818190-2657170

Sonia Chen

全球仪器科技股份有限公司

东城区牛山外经工业区/waijing Industrial zoom,niu shan

dongcheng Town

东莞 - 东城区

China

Delivery Name: 6297305

Ship Date: 20/05/15

MAWB: 909851245885

Customer PO#: RMA



Order Date: 20/05/15

Payment Terms:

Freight Charge:

Freight Terms: NI to pay freight

Incoterms:

Waybill:

Ship Method: SF-Standard

Collect Acct:

Line No.	Part Number	Description	PO Number	Ord	Ship
1.1	150818D-02L	MOD ASSY, PXIE-5644R	RMA	1	1
PRODUCT OF USA					
ECCN:	5B991				
Order Number:	20724987				
Serial Number(s):	F2F0D3				
2.1	198666E-01L	CHASSIS ASSEMBLY, PXIE-1082	RMA	1	1
PRODUCT OF MALAYSIA					
ECCN:	3A992.a				
Order Number:	20724987				
Serial Number(s):	301C208				
3.1	150818C-02L	MOD ASSY, PXIE-5644R	RMA	1	1
PRODUCT OF USA					
ECCN:	5B991				
Order Number:	20724987				
Serial Number(s):	F22BFD				
4.1	150818C-02L	MOD ASSY, PXIE-5644R	RMA	1	1
PRODUCT OF USA					
ECCN:	5B991				
Order Number:	20724987				
Serial Number(s):	F25178				

Gross Weight: 0.00 kg

\*\* Shipping and Handling charges are for the entire order.

Shipping Instructions: None



## Repair Report and Certificate of Conformance

Date Printed: 13-MAY-2015

### Customer

Name: National Instruments Hong Kong (NIH)  
Address: Unit 1305-1310, 13/F., Delta House, No. 3 On Yiu Street  
Shatin, N.T., HK

### Product Returned:

Service Request Number: 1745188  
Repair Order Number: 416049  
Part Number: 150818C-02L  
Description: MOD ASSY, PXIE-5644R  
Serial Number: F25178

### Problem Description Reported:

- SN F25178

测量信号不准, 与信号源输出相差过大

CONTACT: 699523

ISR: Li Li

HK CSC REPAIR

### Repair Report

Repair Area	Repair Performed
Analog Input (RF)	Component Failure -- Replaced Component(s) (Analog Input) (RF)

### Certificate of Conformance, Calibration Certificates & Warranty

This product has been inspected and tested in accordance with National Instruments quality and performance standards. To ensure measurement accuracy, National Instruments calibrates all applicable data acquisition, signal conditioning, and instrumentation hardware products, and then issues Basic Calibration certificates. We no longer ship hardcopies of Basic Calibration certificates since these are available online at [ni.com/calibration](http://ni.com/calibration). National Instruments issues a repair warranty for hardware products against defects in material and workmanship for a period of 90 days or the remainder of the original warranty period, whichever is greater.

Lang Chen  
China Service Center Manager



## Repair Report and Certificate of Conformance

Date Printed: 14-MAY-2015

### Customer

Name: National Instruments Hong Kong (NIH)  
Address: Unit 1305-1310, 13/F., Delta House, No. 3 On Yiu Street  
Shatin, N.T., HK

### Product Returned:

Service Request Number: 1745188  
Repair Order Number: 416047  
Part Number: 150818D-02L  
Description: MOD ASSY, PXIE-5644R  
Serial Number: F2F0D3

### Problem Description Reported:

- SN F2F0D3

Power异常, 自发自收power收不到  
the power supply is unnormal

CONTACT:699523

ISR:Li Li

HK CSC REPAIR

### Repair Report

Repair Area	Repair Performed
Analog Output (RF)	Component Failure -- Replaced Component(s) (Analog Output) (RF)

### Certificate of Conformance, Calibration Certificates & Warranty

This product has been inspected and tested in accordance with National Instruments quality and performance standards. To ensure measurement accuracy, National Instruments calibrates all applicable data acquisition, signal conditioning, and instrumentation hardware products, and then issues Basic Calibration certificates. We no longer ship hardcopies of Basic Calibration certificates since these are available online at [ni.com/calibration](http://ni.com/calibration). National Instruments issues a repair warranty for hardware products against defects in material and workmanship for a period of 90 days or the remainder of the original warranty period, whichever is greater.

Lang Chen  
China Service Center Manager





## Repair Report and Certificate of Conformance

Date Printed: 14-MAY-2015

### Customer

Name: National Instruments Hong Kong (NIH)  
Address: Unit 1305-1310, 13/F., Delta House, No. 3 On Yiu Street  
Shatin, N.T., HK

### Product Returned:

Service Request Number: 1745188  
Repair Order Number: 416052  
Part Number: 150818C-02L  
Description: MOD ASSY, PXIE-5644R  
Serial Number: F22BFD

### Problem Description Reported:

- SN F22BFD  
测量信号不准, 与信号源输出相差过大  
CONTACT:699523  
ISR:Li Li

HK CSC REPAIR

### Repair Report

Repair Area	Repair Performed
Analog Input (RF)	Component Failure -- Replaced Component(s) (Analog Input) (RF)

### Certificate of Conformance, Calibration Certificates & Warranty

This product has been inspected and tested in accordance with National Instruments quality and performance standards. To ensure measurement accuracy, National Instruments calibrates all applicable data acquisition, signal conditioning, and instrumentation hardware products, and then issues Basic Calibration certificates. We no longer ship hardcopies of Basic Calibration certificates since these are available online at [ni.com/calibration](http://ni.com/calibration). National Instruments issues a repair warranty for hardware products against defects in material and workmanship for a period of 90 days or the remainder of the original warranty period, whichever is greater.

Lang Chen  
China Service Center Manager



## Repair Report and Certificate of Conformance

Date Printed: 14-MAY-2015

### Customer

Name: National Instruments Hong Kong (NIH)  
Address: Unit 1305-1310, 13/F., Delta House, No. 3 On Yiu Street  
Shatin, N.T., HK

### Product Returned:

Service Request Number: 1745188  
Repair Order Number: 416048  
Part Number: 198666E-01L  
Description: CHASSIS ASSEMBLY, PXIE-1082  
Serial Number: 301C208

### Problem Description Reported:

- SN 301C208  
机箱在正常开机状态下, 过10分钟左右机器就会突然自动关机。与切换风扇后自动关机。  
CONTACT: 699523  
ISR: Li Li

HK CSC REPAIR

### Repair Report

Repair Area	Repair Performed
Power Supply (PXI VXI Chassis)	Dead Power Supply -- No Outputs

### Certificate of Conformance, Calibration Certificates & Warranty

This product has been inspected and tested in accordance with National Instruments quality and performance standards. To ensure measurement accuracy, National Instruments calibrates all applicable data acquisition, signal conditioning, and instrumentation hardware products, and then issues Basic Calibration certificates. We no longer ship hardcopies of Basic Calibration certificates since these are available online at [ni.com/calibration](http://ni.com/calibration). National Instruments issues a repair warranty for hardware products against defects in material and workmanship for a period of 90 days or the remainder of the original warranty period, whichever is greater.

Lang Chen  
China Service Center Manager