


Fix on next revision

- RGB LED footpring wrong

- Oled display pads should be pushed up towards top



LCSC C88334

