

CONTROLLER INTERFACE SIGNALS

ANALOG INPUTS: VACOUT_MEAS; IACOUT_MEAS; TEMP_MEAS1; TEMP_MEAS2; TEMP_MEAS3

DIGITAL INPUTS: OVER_I; OVER_ILEAK

PWM OUTPUTS: Q_TOP

DIGITAL OUTPUTS: Q_ENABLE; LED1; LED2

