

1. Pinouts for relay are not correct. Use example connections for your situation. The HK19F is a 5V relay coil.
2. Some key pads may use a series resistor to multiplex the lamp and the door opener.
3. Project Testend on Gene: GXL9550CL

Door series resistor 100ohms
Lamp Series resistor 50ohms

