


TMC2130 with
Homing PIN
removed on both
Z axis

Driver placement



X- TMC2130 SPI

Y- TMC2130 SPI

Z-TMC2130
Sensorless
homing PIN
removed

E - A4988

Z2-TMC2130
Sensorless
homing PIN
removed



1st two pins have jumpers

(Z2) Top 2 pins connected across the board TMC 2130-No Homing PIN

(E) A4988- Skip 1st two on the bottom row. All other on the bottom row connected

(Z) Top 2 pins connected across the board TMC2130-No Homing PIN

Everything in place

