


Item	P	I	Risk (P*I)	Recognized	Mitigated/ Resolved	ROAM
Falling Behind	20	70	1400	20-Mar-23	3-Apr-23	O
Not being able to produce a functioning project	8	70	560	20-Mar-23	3-Apr-23	O
			0			
			0			
			0			
			0			
			0			
			0			
			0			



How

Gaining a strong understanding of the project at the beginning. Using spring break to start the project and running into issues early

Unit testing at every level of functionality

--