

01



00

00

00

00

00

00



00

00

INSPECTION LIST REVISION #1 SWELLENDAM RAILTON CDC GENERAL MAINTENANCE (ALPHA) ELECTRICAL AND ELECTRONIC SERVICES MS/810001-0109

E5177
06 October 2023


ROOM 06



Missing Endcap to be fitted.



Missing endcap to be fitted.



Missing endcap to be fitted.

PHOTO TIMESTAMP: 2023-10-03 10:16:17
GPS LAT: -34.0348 / GPS LONG: 20.4448

PHOTO TIMESTAMP: 2023-10-03 10:16:25
GPS LAT: coords_lat / GPS LONG: coords_long

PHOTO TIMESTAMP: 2023-10-03 10:16:44
GPS LAT: coords_lat / GPS LONG: coords_long



Silicon gap between wall and powerskirting.



Once the new telephone and Data points are installed by Electronics contractor the old lines may be removed.



Once the new telephone and Data points are installed the old points points can be disconnected and removed.

PHOTO TIMESTAMP: 2023-10-03 10:16:50
GPS LAT: coords_lat / GPS LONG: coords_long


PHOTO TIMESTAMP: 2023-10-03 10:17:00
GPS LAT: coords_lat / GPS LONG: coords_long

PHOTO TIMESTAMP: 2023-10-03 10:17:09
GPS LAT: coords_lat / GPS LONG: coords_long

ELECTRICAL: LIGHTING, POWER, WIREWAYS
ELECTRONIC: DATA, ACCESS CONTROL, PA, ALARM
BUILDER

BCX
N/A
N/A

BCX
N/A
N/A



Missing combination socket outlet.






New luminaires to be installed per revised drawing.

PHOTO TIMESTAMP: 2023-10-03 10:17:19
GPS LAT: coords_lat / GPS LONG: coords_long

PHOTO TIMESTAMP: 2023-10-03 10:17:47
GPS LAT: -34.0349 / GPS LONG: 20.4447

ROOM 07




Missing combination socket outlet.

PHOTO TIMESTAMP: 2023:10:03 10:51:01
GPS LAT: -34.0349 / GPS LONG: 20.4447



Missing end cap.

PHOTO TIMESTAMP: 2023:10:03 10:51:13
GPS LAT: coords_lat / GPS LONG: coords_long



Missing end cap.

PHOTO TIMESTAMP: 2023:10:03 10:51:27
GPS LAT: coords_lat / GPS LONG: coords_long




Once new Data and telephone points are installed by Electronics contractor, old telephone and data wiring can be removed.

PHOTO TIMESTAMP: 2023:10:03 10:51:38
GPS LAT: coords_lat / GPS LONG: coords_long



Once electronic contractor is appointed the PIR needs to be rewired.

PHOTO TIMESTAMP: 2023:10:03 10:51:38
GPS LAT: -34.0348 / GPS LONG: 20.4448



Once new data and telephone points are installed by electronics contractor the old points can be removed.

PHOTO TIMESTAMP: 2023:10:03 10:51:41
GPS LAT: -34.0348 / GPS LONG: 20.4449

RED	ELECTRICAL: LIGHTING, POWER, WIREWAYS	CYAN	BCX
YELLOW	ELECTRONIC: DATA, ACCESS CONTROL, PA, ALARM	BLUE	N/A
GREEN	BUILDER	MAGENTA	N/A



Missing earth on SANS 164-2 outlet.

PHOTO TIMESTAMP: 2023-10-03 13:31:29
GPS LAT: -34.0348 / GPS LONG: 20.4448