


PCB Layout, Bottom Layer 1:1



BE SURE TO PRINT AT 100% SCALE


Gnusbduino

Open Source USB Sensor Board
by Michael Egger, [a n y m a]
gnusb.sourceforge.net

Version 2012-12-06

Drills & Parts placement, solder side

Drills: 0.8mm unless otherwise noted



Schematic

