



Adjust value of resistors  
as high as possible to  
increase battery life.  
Decrease it to increase  
brightness. Min 220 Ω.