

FUI-CMP-73 Program Specific Data**Created: 10/30/2015 03:21:38 PM Updated: 10/30/2015 03:26:56 PM**

ID:	FUI-CMP-73
Name:	Program Specific Data
Description:	
Change Request:	
Export Controlled:	Not Used
DOORS ID:	
Versions:	2 1

FUI-CMP-75 M170**Created: 10/30/2015 03:26:14 PM Updated: 10/30/2015 03:26:14 PM**

ID:	FUI-CMP-75
Name:	M170
Description:	
Change Request:	
Export Controlled:	Not Used
DOORS ID:	
Versions:	1

FUI-SET-129 Low Level Software Requirements**Created: 01/15/2016 02:32:46 PM Updated: 01/15/2016 02:32:46 PM**

ID:	FUI-SET-129
Set Key:	LLSWReq
Name:	Low Level Software Requirements
Description:	
Change Request:	
Export Controlled:	Not Used
DOORS ID:	
Versions:	1

FUI-FLD-5290 FUI Util**Created: 03/11/2016 12:14:39 PM Updated: 03/11/2016 12:14:39 PM**

ID:	FUI-FLD-5290
Name:	FUI Util
Description:	
Change Request:	
Export Controlled:	Not Used
DOORS ID:	
Versions:	1

FUI-FLD-20922 Fui_Api_Prod**Created: 07/10/2017 10:51:25 PM Updated: 07/10/2017 10:51:25 PM**

ID:	FUI-FLD-20922
Name:	Fui_Api_Prod
Description:	
Change Request:	
Export Controlled:	Not Used
DOORS ID:	
Versions:	1

FUI-LLSWReq-2547 Fui_Api_Prod.Output_Active_Formats**Created: 07/10/2017 10:57:27 PM Updated: 07/27/2017 02:40:55 PM**

Project ID:	FUI-LLSWReq-2547
Global ID:	COL03-LLSWReq-8282402
Status:	Proposed

Requirement Summary:	Fui_Api_Prod.Output_Active_Formats
Requirement Description:	http://svn/fms-dev/fms/branches/int/FMSA_M170_INT/fui/requirements_and_design/requirements/Low_Level_Requirements/FUI_UTIL/Fui_Api_Prod.xml SVN Revision: 244288
isSafety?:	No
isDerived?:	Yes
isSecurity?:	Unassigned
Derived Rationale:	see model requirement for derived rationale
DAL:	B
Commentary:	
Relationship:	
Export Controlled:	Not Used
DOORS ID:	
Verification Method:	Test
Versions:	4 3 2 1

Upstream Relationships

Item ID	Name	Project	Relationship	Path
FUI-FusionCR-2482	WE FMSA-74848: Update SW LLR for FMSA - M170 - Build doesn't come up due to constraint error from FUI APIs	FMS FUI	Changes	Program Specific Data\M170\Fusion Change Requests\M170 Fusion Change Requests\ WP FMSA-74807\

Downstream Relationships

Item ID	Name	Project	Relationship	Path
FUI-DO178BCTestObjB-13783	Fui_Api_Prod.xlsm	FMS FUI	Traces	Program Specific Data\M170\Low Level Software Requirements\FUI Util\Fui_Api_Prod\

FUI-LLSWReq-2548 Fui_Api_Prod.Retrieve_Active_Master_Layer**Created: 07/10/2017 10:59:03 PM Updated: 07/27/2017 02:40:55 PM**

Project ID:	FUI-LLSWReq-2548
Global ID:	COL03-LLSWReq-8282403
Status:	Proposed
Requirement Summary:	Fui_Api_Prod.Retrieve_Active_Master_Layer
Requirement Description:	http://svn/fms-dev/fms/branches/int/FMSA_M170_INT/fui/requirements_and_design/requirements/Low_Level_Requirements/FUI_UTIL/Fui_Api_Prod.xml SVN Revision: 244288
isSafety?:	No
isDerived?:	Yes
isSecurity?:	Unassigned
Derived Rationale:	see model requirement for derived rationale
DAL:	B
Commentary:	
Relationship:	
Export Controlled:	Not Used
DOORS ID:	
Verification Method:	Test
Versions:	4 3 2 1

Upstream Relationships

Item ID	Name	Project	Relationship	Path
FUI-FusionCR-2482	WE FMSA-74848: Update SW LLR for FMSA - M170 - Build doesn't come up due to constraint error from FUI APIs	FMS FUI	Changes	Program Specific Data\M170\Fusion Change Requests\M170 Fusion Change Requests\ WP FMSA-74807\

Downstream Relationships

Item ID	Name	Project	Relationship	Path
FUI-DO178BCTestObjB-13783	Fui_Api_Prod.xlsm	FMS FUI	Traces	Program Specific Data\M170\Low Level Software Requirements\FUI Util\Fui_Api_Prod\

FUI-LLSWReq-2549 [Fui_Api_Prod.Retrieve_VSpeed_Thrust_Data](#)**Created: 07/10/2017 11:03:09 PM Updated: 07/27/2017 02:40:55 PM**

Project ID:	FUI-LLSWReq-2549
Global ID:	COL03-LLSWReq-8282404
Status:	Proposed
Requirement Summary:	Fui_Api_Prod.Retrieve_VSpeed_Thrust_Data
Requirement Description:	http://asvn/fms-dev/fms/branches/int/FMSA_M170_INT/fui/requirements_and_design/requirements/Low_Level_Requirements/FUI_UTIL/Fui_Api_Prod.xml SVN Revision: 244288
isSafety?:	No
isDerived?:	Yes
isSecurity?:	Unassigned
Derived Rationale:	see model requirement for derived rationale
DAL:	B
Commentary:	
Relationship:	
Export Controlled:	Not Used
DOORS ID:	
Verification Method:	Test
Versions:	5 4 3 2 1

Upstream Relationships

Item ID	Name	Project	Relationship	Path
FUI-FusionCR-2482	WE FMSA-74848: Update SW LLR for FMSA - M170 - Build doesn't come up due to constraint error from FUI APIs	FMS FUI	Changes	Program Specific Data\M170\Fusion Change Requests\M170 Fusion Change Requests\ WP FMSA-74807\

Downstream Relationships

Item ID	Name	Project	Relationship	Path
FUI-DO178BCTestObjB-13783	Fui_Api_Prod.xlsm	FMS FUI	Traces	Program Specific Data\M170\Low Level Software Requirements\FUI Util\Fui_Api_Prod\