


## EWMA Chart for x



Number of groups = 30

Center = 10

StdDev = 1.2

Smoothing parameter = 0.1

Control limits at  $2.7 \times \text{sigma}$

No. of points beyond limits = 0