



3) Rev1: Fix I2C lines to SI5351
2) All 74LS Parts could be substituted by 74HCT
1) All 74HC parts could be substituted by 74HCT

Sheet: /
File: z80-SOUND_rev1.kicad_sch

Title: Z8C Audio Interface

| | | |
|--------------------|------------------|---------|
| Size: A3 | Date: 2022-10-14 | Rev: 1 |
| KiCad E.D.A. 8.0.7 | | Id: 1/1 |