


Motorola GM950 Conventional Radio RSS

File Edit Service Options Window Help



Personality Validation

Error: Memory Channel selected with no button assigned
Error: Call 1 Tone selected with no button or GP I/O line assigned
Error: Call 2 Tone selected with no button or GP I/O line assigned
Information: Channel 1
Error: Call 1 Tone selected with no button or GP I/O line assigned
Error: Call 2 Tone selected with no button or GP I/O line assigned
Error: DPL TOC selected with invalid PL Encode Mode
Information: Channel 2
Error: Call 1 Tone selected with no button or GP I/O line assigned
Error: Call 2 Tone selected with no button or GP I/O line assigned
Information: Channel 3
Error: Call 1 Tone selected with no button or GP I/O line assigned
Error: Call 2 Tone selected with no button or GP I/O line assigned
Information: Channel 4
Error: Call 1 Tone selected with no button or GP I/O line assigned
Error: Call 2 Tone selected with no button or GP I/O line assigned
Information: Channel 5
Error: Call 1 Tone selected with no button or GP I/O line assigned
Error: Call 2 Tone selected with no button or GP I/O line assigned
Information: Channel 6
Error: Call 1 Tone selected with no button or GP I/O line assigned
Error: Call 2 Tone selected with no button or GP I/O line assigned
Information: Channel 7
Error: Call 1 Tone selected with no button or GP I/O line assigned
Error: Call 2 Tone selected with no button or GP I/O line assigned
Information: Channel 8
Error: Call 1 Tone selected with no button or GP I/O line assigned
Error: Call 2 Tone selected with no button or GP I/O line assigned
Information: Channel 9

OK