

Inspection Report - Flat 1001

Project: -
Building: Tower 1
Floor: Floor 1
Flattype: 3bhk
Generated On: 31-07-2025

Summary

<div>68</div> <div>TOTAL CHECKPOINTS</div>	<div>38</div> <div>PENDING</div>
<div>22</div> <div>COMPLETED</div>	<div>0</div> <div>REJECTED</div>

Checklist: Civil Checklist

QUESTION	STATUS	ATTEMPT DETAILS
Check for cracks	COMPLETED (2 attempts)	Attempt 1
		CHECKER Mukesh Tiwari Status: Rejected_By_Checker 28-07-2025 07:46
		Attempt 2
		MAKER Mukesh Tiwari 28-07-2025 07:48
Are safety signs visible?	COMPLETED (1 attempt)	SUPERVISOR Mukesh Tiwari 29-07-2025 15:46
		CHECKER Mukesh Tiwari Status: Completed 30-07-2025 09:58
		Attempt 1
		CHECKER Mukesh Tiwari Status: Completed Remarks: done 28-07-2025 07:46

QUESTION

STATUS

ATTEMPT DETAILS

Check door
operation

COMPLETED

(1 attempt)

Attempt 1

CHECKER

Mukesh Tiwari

Status: Completed

Remarks: donee

28-07-2025 07:47

Checklist: testing

QUESTION	STATUS	ATTEMPT DETAILS
What is the quality?	COMPLETED (1 attempt)	Attempt 1
		CHECKER Mukesh Tiwari Status: Completed 29-07-2025 14:53
Is the material approved?	COMPLETED (2 attempts)	Attempt 1
		CHECKER Mukesh Tiwari Status: Rejected_By_Checker 29-07-2025 14:53
		Attempt 2
		MAKER Mukesh Tiwari 29-07-2025 14:54
		SUPERVISOR Mukesh Tiwari 29-07-2025 15:35
		CHECKER Mukesh Tiwari Status: Completed 29-07-2025 15:46
Check alignment	COMPLETED (3 attempts)	Attempt 1
		CHECKER Mukesh Tiwari Status: Rejected_By_Checker 29-07-2025 14:53

QUESTION	STATUS	ATTEMPT DETAILS
		Attempt 2
		MAKER Mukesh Tiwari 29-07-2025 14:54
		SUPERVISOR Mukesh Tiwari 29-07-2025 15:36
		CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor
		Attempt 3
		MAKER Mukesh Tiwari 29-07-2025 15:44
		SUPERVISOR Mukesh Tiwari 29-07-2025 15:45
		CHECKER Mukesh Tiwari Status: Completed 29-07-2025 15:47
Is the site clean?	COMPLETED (3 attempts)	Attempt 1 CHECKER Mukesh Tiwari Status: Rejected_By_Checker 29-07-2025 14:53

QUESTION	STATUS	ATTEMPT DETAILS
		Attempt 2
		MAKER Mukesh Tiwari 29-07-2025 14:55
		SUPERVISOR Mukesh Tiwari 29-07-2025 15:36
		CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor
		Attempt 3
		MAKER Mukesh Tiwari 29-07-2025 15:44
		SUPERVISOR Mukesh Tiwari 29-07-2025 15:45
		CHECKER Mukesh Tiwari Status: Completed 29-07-2025 15:47
Verify measurements	COMPLETED (2 attempts)	Attempt 1 CHECKER Mukesh Tiwari Status: Rejected_By_Checker 29-07-2025 14:53

QUESTION	STATUS	ATTEMPT DETAILS
		<div>Attempt 2</div> <div> MAKER Mukesh Tiwari 29-07-2025 14:55 </div> <div> SUPERVISOR Mukesh Tiwari 29-07-2025 15:36 </div> <div> CHECKER Mukesh Tiwari Status: Completed 30-07-2025 09:59 </div>
Is the paint uniform?	<div>COMPLETED</div> <div>(2 attempts)</div>	<div>Attempt 1</div> <div> CHECKER Mukesh Tiwari Status: Rejected_By_Checker 29-07-2025 14:53 </div>
		<div>Attempt 2</div> <div> MAKER Mukesh Tiwari 29-07-2025 14:55 </div> <div> SUPERVISOR Mukesh Tiwari 29-07-2025 15:36 </div> <div> CHECKER Mukesh Tiwari Status: Completed 30-07-2025 09:59 </div>

QUESTION	STATUS	ATTEMPT DETAILS
Check for cracks	COMPLETED (3 attempts)	Attempt 1
		CHECKER Mukesh Tiwari Status: Rejected_By_Checker 29-07-2025 14:54
		Attempt 2
		MAKER Mukesh Tiwari 29-07-2025 14:55
		SUPERVISOR Mukesh Tiwari 29-07-2025 15:36
		CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor
		Attempt 3
		MAKER Mukesh Tiwari 29-07-2025 15:44
		SUPERVISOR Mukesh Tiwari 29-07-2025 15:45
		CHECKER Mukesh Tiwari Status: Completed 30-07-2025 09:59

QUESTION	STATUS	ATTEMPT DETAILS
Are safety signs visible?	COMPLETED (2 attempts)	Attempt 1
		CHECKER Mukesh Tiwari Status: Rejected_By_Checker 29-07-2025 14:54
		Attempt 2
		MAKER Mukesh Tiwari 29-07-2025 14:55
Is the wiring secured?	PENDING_FOR_SUPERVISOR (5 attempts)	SUPERVISOR Mukesh Tiwari 29-07-2025 15:36
		CHECKER Mukesh Tiwari Status: Completed 30-07-2025 09:59
		Attempt 1
		CHECKER Mukesh Tiwari Status: Rejected_By_Checker 29-07-2025 14:54

QUESTION

STATUS

ATTEMPT DETAILS

Attempt 2

MAKER

Mukesh Tiwari

29-07-2025 14:55

SUPERVISOR

Mukesh Tiwari

29-07-2025 15:36

CHECKER

Mukesh Tiwari

Status: Rejected_By_Supervisor

Attempt 3

MAKER

Mukesh Tiwari

29-07-2025 15:44

SUPERVISOR

Mukesh Tiwari

29-07-2025 15:45

CHECKER

Mukesh Tiwari

Status: Rejected_By_Checker

30-07-2025 09:59

QUESTION	STATUS	ATTEMPT DETAILS
		Attempt 4
		MAKER Mukesh Tiwari 30-07-2025 10:00
		SUPERVISOR Mukesh Tiwari 30-07-2025 10:58
		CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor
		Attempt 5
		MAKER Mukesh Tiwari 30-07-2025 13:08
		SUPERVISOR Mukesh Tiwari
		CHECKER Mukesh Tiwari Status: Pending_Supervisor
		Attempt 1
Check door operation	TETMPORY_INSPECTION (4 attempts)	CHECKER Mukesh Tiwari Status: Rejected_By_Checker 29-07-2025 14:54

QUESTION**STATUS****ATTEMPT DETAILS****Attempt 2****MAKER****Mukesh Tiwari**

29-07-2025 14:55

SUPERVISOR**Mukesh Tiwari**

29-07-2025 15:36

CHECKER**Mukesh Tiwari**

Status: Rejected_By_Supervisor

Attempt 3**MAKER****Mukesh Tiwari**

29-07-2025 15:44

SUPERVISOR**Mukesh Tiwari**

29-07-2025 15:46

CHECKER**Mukesh Tiwari**

Status: Rejected_By_Checker

30-07-2025 09:59

QUESTION

STATUS

ATTEMPT DETAILS

Attempt 4

MAKER

Mukesh Tiwari

30-07-2025 10:00

SUPERVISOR

Mukesh Tiwari

30-07-2025 10:59

CHECKER

Mukesh Tiwari

Status: Pending_Checker

Checklist: Plumbing Checklist

QUESTION	STATUS	ATTEMPT DETAILS
Verify measurements	PENDING_FOR_MAKER (2 attempts)	Attempt 1 CHECKER Mukesh Tiwari Status: Rejected_By_Checker 30-07-2025 13:26
		Attempt 2 CHECKER Mukesh Tiwari Status: Created
Is the paint uniform?	PENDING_FOR_MAKER (2 attempts)	Attempt 1 CHECKER Mukesh Tiwari Status: Rejected_By_Checker 30-07-2025 13:27
		Attempt 2 CHECKER Mukesh Tiwari Status: Created
Check for cracks	COMPLETED (1 attempt)	Attempt 1 CHECKER Mukesh Tiwari Status: Completed 31-07-2025 11:28

QUESTION	STATUS	ATTEMPT DETAILS
Are safety signs visible?	PENDING_FOR_INSPECTOR (0 attempts)	No submissions
Check door operation	PENDING_FOR_INSPECTOR (0 attempts)	No submissions

Checklist: Flat 906 Final Handover QC

QUESTION	STATUS	ATTEMPT DETAILS
Living Room Paint Quality	PENDING_FOR_MAKER (0 attempts)	No submissions
Bathroom Fixtures Installation	PENDING_FOR_MAKER (0 attempts)	No submissions
Entrance Door Security	PENDING_FOR_MAKER (0 attempts)	No submissions

Checklist: Flat 906 Final Handover QC

QUESTION	STATUS	ATTEMPT DETAILS
Living Room Paint Quality	PENDING_FOR_MAKER (0 attempts)	No submissions
Bathroom Fixtures Installation	PENDING_FOR_MAKER (0 attempts)	No submissions
Entrance Door Security	PENDING_FOR_MAKER (0 attempts)	No submissions

Checklist: xcfghj---testing

QUESTION	STATUS	ATTEMPT DETAILS
What is the quality?	PENDING_FOR_SUPERVISOR (2 attempts)	<div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Rejected_By_Checker</div><div>Remarks: Bulk FAIL decision by CHECKER</div><div>30-07-2025 10:56</div></div>
		Attempt 2
		<div><div>MAKER</div><div>Mukesh Tiwari</div><div>30-07-2025 10:57</div></div> <div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Pending_Supervisor</div></div>
Is the material approved?	PENDING_FOR_SUPERVISOR (2 attempts)	<div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Rejected_By_Checker</div><div>Remarks: Bulk FAIL decision by CHECKER</div><div>30-07-2025 10:56</div></div>
		Attempt 2
		<div><div>MAKER</div><div>Mukesh Tiwari</div><div>30-07-2025 13:04</div></div> <div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Pending_Supervisor</div></div>

QUESTION	STATUS	ATTEMPT DETAILS
Check alignment	PENDING_FOR_SUPERVISOR (2 attempts)	<div>CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 10:56</div>
		Attempt 2
		<div>MAKER Mukesh Tiwari 30-07-2025 13:04</div> <div>CHECKER Mukesh Tiwari Status: Pending_Supervisor</div>
Is the site clean?	PENDING_FOR_SUPERVISOR (2 attempts)	<div>CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 10:56</div>
		Attempt 2
		<div>MAKER Mukesh Tiwari 30-07-2025 13:04</div> <div>CHECKER Mukesh Tiwari Status: Pending_Supervisor</div>

QUESTION	STATUS	ATTEMPT DETAILS
Verify measurements	PENDING_FOR_SUPERVISOR (2 attempts)	<div>Attempt 1</div> <div>CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 10:56</div>
		<div>Attempt 2</div> <div>MAKER Mukesh Tiwari 30-07-2025 13:04</div> <div>CHECKER Mukesh Tiwari Status: Pending_Supervisor</div>
Is the paint uniform?	PENDING_FOR_SUPERVISOR (2 attempts)	<div>Attempt 1</div> <div>CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 10:56</div>
		<div>Attempt 2</div> <div>MAKER Mukesh Tiwari 30-07-2025 13:04</div> <div>CHECKER Mukesh Tiwari Status: Pending_Supervisor</div>


QUESTION	STATUS	ATTEMPT DETAILS
Check for cracks	PENDING_FOR_SUPERVISOR (2 attempts)	<div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Rejected_By_Checker</div><div>Remarks: Bulk FAIL decision by CHECKER</div><div>30-07-2025 10:56</div></div>
		<div>Attempt 2</div> <div><div>MAKER</div><div>Mukesh Tiwari</div><div>30-07-2025 13:04</div></div> <div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Pending_Supervisor</div></div>
Are safety signs visible?	PENDING_FOR_SUPERVISOR (2 attempts)	<div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Rejected_By_Checker</div><div>Remarks: Bulk FAIL decision by CHECKER</div><div>30-07-2025 10:56</div></div>
		<div>Attempt 2</div> <div><div>MAKER</div><div>Mukesh Tiwari</div><div>30-07-2025 13:04</div></div> <div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Pending_Supervisor</div></div>

QUESTION	STATUS	ATTEMPT DETAILS
Is the wiring secured?	PENDING_FOR_SUPERVISOR (2 attempts)	<div>CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 10:56</div>
		Attempt 2
		<div>MAKER Mukesh Tiwari 30-07-2025 13:04</div> <div>CHECKER Mukesh Tiwari Status: Pending_Supervisor</div>
Check door operation	PENDING_FOR_SUPERVISOR (2 attempts)	<div>CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 10:56</div>
		Attempt 2
		<div>MAKER Mukesh Tiwari 30-07-2025 13:04</div> <div>CHECKER Mukesh Tiwari Status: Pending_Supervisor</div>

Checklist: Flat 906 Final Handover QC


QUESTION	STATUS	ATTEMPT DETAILS
Living Room Paint Quality	PENDING_FOR_MAKER (0 attempts)	No submissions
Bathroom Fixtures Installation	PENDING_FOR_MAKER (0 attempts)	No submissions
Entrance Door Security	PENDING_FOR_MAKER (0 attempts)	No submissions

Checklist: Flat 906 Final Handover QC

QUESTION	STATUS	ATTEMPT DETAILS
Living Room Paint Quality	PENDING_FOR_SUPERVISOR (2 attempts)	<div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Rejected_By_Checker</div><div>30-07-2025 11:05</div></div>
		<div>Attempt 2</div> <div><div>MAKER</div><div>Mukesh Tiwari</div><div>31-07-2025 06:32</div><div></div></div> <div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Pending_Supervisor</div></div>
Bathroom Fixtures Installation	PENDING_FOR_SUPERVISOR (2 attempts)	<div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Rejected_By_Checker</div><div>30-07-2025 11:05</div></div>

QUESTION	STATUS	ATTEMPT DETAILS
		<div>Attempt 2</div> <div><div>MAKER</div><div>Mukesh Tiwari</div><div>31-07-2025 06:32</div></div> <div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Pending_Supervisor</div></div>

Entrance Door Security	<div>PENDING_FOR_SUPERVISOR</div> <div>(2 attempts)</div>	<div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Rejected_By_Checker</div><div>30-07-2025 11:05</div></div>
------------------------	---	--

		<div>Attempt 2</div> <div><div>MAKER</div><div>Mukesh Tiwari</div><div>31-07-2025 06:32</div><div></div></div> <div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Pending_Supervisor</div></div>
--	--	---

Checklist: Flat 906 Final Handover QC

QUESTION**STATUS****ATTEMPT DETAILS**

**Living Room Paint
Quality D**One hai
kya

PENDING_FOR_SUPERVISOR

(2 attempts)

CHECKER**Mukesh Tiwari**


Status: Rejected_By_Checker

Remarks: Initial QC failed for 2 items. Needs rectification.

30-07-2025 11:14

Attempt 2**MAKER****Mukesh Tiwari**

31-07-2025 06:32

**CHECKER****Mukesh Tiwari**

Status: Pending_Supervisor

**Bathroom Fixtures
Installation**

PENDING_FOR_SUPERVISOR

(2 attempts)

CHECKER**Mukesh Tiwari**

Status: Rejected_By_Checker

Remarks: Initial QC failed for 2 items. Needs rectification.

30-07-2025 11:14

QUESTION	STATUS	ATTEMPT DETAILS
		<div>Attempt 2</div> <div><div>MAKER</div><div>Mukesh Tiwari</div><div>31-07-2025 06:32</div></div> <div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Pending_Supervisor</div></div>

Entrance Door Security	<div>PENDING_FOR_SUPERVISOR</div> <div>(2 attempts)</div>	<div>CHECKER</div> <div>Mukesh Tiwari</div> <div>Status: Rejected_By_Checker</div> <div>Remarks: Initial QC failed for 2 items. Needs rectification.</div> <div>30-07-2025 11:14</div>
------------------------	---	--

		<div>Attempt 2</div> <div><div>MAKER</div><div>Mukesh Tiwari</div><div>31-07-2025 06:32</div></div> <div><div>CHECKER</div><div>Mukesh Tiwari</div><div>Status: Pending_Supervisor</div></div>
--	--	--

Checklist: testing chechlistzs by vaSUIJII

QUESTION	STATUS	ATTEMPT DETAILS
What is the quality?	PENDING_FOR_SUPERVISOR (3 attempts)	CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 13:03
		Attempt 2
		MAKER Mukesh Tiwari 30-07-2025 13:04
		SUPERVISOR Mukesh Tiwari 30-07-2025 13:06
		CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor
		Attempt 3
		MAKER Mukesh Tiwari 30-07-2025 13:08
		SUPERVISOR Mukesh Tiwari
		CHECKER Mukesh Tiwari Status: Pending_Supervisor

QUESTION	STATUS	ATTEMPT DETAILS
Is the material approved?	PENDING_FOR_SUPERVISOR (3 attempts)	CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 13:03
		Attempt 2
		MAKER Mukesh Tiwari 30-07-2025 13:04
		SUPERVISOR Mukesh Tiwari 30-07-2025 13:06
		CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor
		Attempt 3
		MAKER Mukesh Tiwari 30-07-2025 13:08
		SUPERVISOR Mukesh Tiwari
		CHECKER Mukesh Tiwari Status: Pending_Supervisor

QUESTION	STATUS	ATTEMPT DETAILS
Check alignment	PENDING_FOR_SUPERVISOR (3 attempts)	<div>CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 13:03</div>
		Attempt 2
		<div>MAKER Mukesh Tiwari 30-07-2025 13:04</div>
		<div>SUPERVISOR Mukesh Tiwari 30-07-2025 13:06</div>
		<div>CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor</div>
		Attempt 3
		<div>MAKER Mukesh Tiwari 30-07-2025 13:08</div>
		<div>SUPERVISOR Mukesh Tiwari</div>
		<div>CHECKER Mukesh Tiwari Status: Pending_Supervisor</div>

QUESTION	STATUS	ATTEMPT DETAILS
Is the site clean?	PENDING_FOR_SUPERVISOR (3 attempts)	CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 13:03
		Attempt 2
		MAKER Mukesh Tiwari 30-07-2025 13:04
		SUPERVISOR Mukesh Tiwari 30-07-2025 13:06
		CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor
		Attempt 3
		MAKER Mukesh Tiwari 30-07-2025 13:08
		SUPERVISOR Mukesh Tiwari
		CHECKER Mukesh Tiwari Status: Pending_Supervisor

QUESTION	STATUS	ATTEMPT DETAILS
Verify measurements	PENDING_FOR_SUPERVISOR (3 attempts)	<div>CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 13:03</div>
		Attempt 2
		<div>MAKER Mukesh Tiwari 30-07-2025 13:04</div>
		<div>SUPERVISOR Mukesh Tiwari 30-07-2025 13:06</div>
		<div>CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor</div>
		Attempt 3
		<div>MAKER Mukesh Tiwari 30-07-2025 13:08</div>
		<div>SUPERVISOR Mukesh Tiwari</div>
		<div>CHECKER Mukesh Tiwari Status: Pending_Supervisor</div>

QUESTION	STATUS	ATTEMPT DETAILS
Is the paint uniform?	PENDING_FOR_SUPERVISOR (3 attempts)	CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 13:03
		Attempt 2
		MAKER Mukesh Tiwari 30-07-2025 13:04
		SUPERVISOR Mukesh Tiwari 30-07-2025 13:07
		CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor
		Attempt 3
		MAKER Mukesh Tiwari 30-07-2025 13:08
		SUPERVISOR Mukesh Tiwari
		CHECKER Mukesh Tiwari Status: Pending_Supervisor

QUESTION	STATUS	ATTEMPT DETAILS
Check for cracks	PENDING_FOR_SUPERVISOR (3 attempts)	<div>CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 13:03</div>
		Attempt 2
		<div>MAKER Mukesh Tiwari 30-07-2025 13:04</div>
		<div>SUPERVISOR Mukesh Tiwari 30-07-2025 13:07</div>
		<div>CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor</div>
		Attempt 3
		<div>MAKER Mukesh Tiwari 30-07-2025 13:08</div>
		<div>SUPERVISOR Mukesh Tiwari</div>
		<div>CHECKER Mukesh Tiwari Status: Pending_Supervisor</div>

QUESTION	STATUS	ATTEMPT DETAILS
Are safety signs visible?	PENDING_FOR_SUPERVISOR (3 attempts)	<div>CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 13:03</div>
		Attempt 2
		<div>MAKER Mukesh Tiwari 30-07-2025 13:04</div>
		<div>SUPERVISOR Mukesh Tiwari 30-07-2025 13:07</div>
		<div>CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor</div>
		Attempt 3
		<div>MAKER Mukesh Tiwari 30-07-2025 13:08</div>
		<div>SUPERVISOR Mukesh Tiwari</div>
		<div>CHECKER Mukesh Tiwari Status: Pending_Supervisor</div>

QUESTION	STATUS	ATTEMPT DETAILS
Is the wiring secured?	PENDING_FOR_SUPERVISOR (3 attempts)	CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 13:03
		Attempt 2
		MAKER Mukesh Tiwari 30-07-2025 13:04
		SUPERVISOR Mukesh Tiwari 30-07-2025 13:07
		CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor
		Attempt 3
		MAKER Mukesh Tiwari 30-07-2025 13:08
		SUPERVISOR Mukesh Tiwari
		CHECKER Mukesh Tiwari Status: Pending_Supervisor

QUESTION	STATUS	ATTEMPT DETAILS
Check door operation	PENDING_FOR_SUPERVISOR (3 attempts)	CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 30-07-2025 13:03
		Attempt 2
		MAKER Mukesh Tiwari 30-07-2025 13:05
		SUPERVISOR Mukesh Tiwari 30-07-2025 13:07
		CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor
		Attempt 3
		MAKER Mukesh Tiwari 30-07-2025 13:08
		SUPERVISOR Mukesh Tiwari
		CHECKER Mukesh Tiwari Status: Pending_Supervisor

Checklist: new checklist

QUESTION	STATUS	ATTEMPT DETAILS
Is the paint uniform?	PENDING_FOR_INSPECTOR (0 attempts)	No submissions
Check for cracks	PENDING_FOR_INSPECTOR (0 attempts)	No submissions
Are safety signs visible?	PENDING_FOR_INSPECTOR (0 attempts)	No submissions
Is the wiring secured?	PENDING_FOR_INSPECTOR (0 attempts)	No submissions
Check door operation	PENDING_FOR_INSPECTOR (0 attempts)	No submissions

Checklist: checklist-lecevl-final testing

QUESTION

STATUS

ATTEMPT DETAILS

What is the
quality?

COMPLETED

(3 attempts)

Attempt 1

CHECKER

Mukesh Tiwari

Status: Rejected_By_Checker

Remarks: Bulk FAIL decision by CHECKER

31-07-2025 12:54

Attempt 2

MAKER

Mukesh Tiwari

Remarks: done

31-07-2025 12:55



SUPERVISOR

Mukesh Tiwari

31-07-2025 12:57

CHECKER

Mukesh Tiwari

Status: Rejected_By_Supervisor

QUESTION**STATUS****ATTEMPT DETAILS****Attempt 3****MAKER****Mukesh Tiwari**

Remarks: sxZ

31-07-2025 13:01

**SUPERVISOR****Mukesh Tiwari**

31-07-2025 13:02

CHECKER**Mukesh Tiwari**

Status: Completed

Remarks: Bulk PASS decision by CHECKER

31-07-2025 13:05

**Is the material
approved?****COMPLETED**

(3 attempts)

Attempt 1**CHECKER****Mukesh Tiwari**

Status: Rejected_By_Checker

Remarks: Bulk FAIL decision by CHECKER

31-07-2025 12:54

QUESTION**STATUS****ATTEMPT DETAILS****Attempt 2****MAKER****Mukesh Tiwari**

Remarks: done

31-07-2025 12:55

**SUPERVISOR****Mukesh Tiwari**

31-07-2025 12:57

CHECKER**Mukesh Tiwari**

Status: Rejected_By_Supervisor

Attempt 3**MAKER****Mukesh Tiwari**

31-07-2025 13:01

SUPERVISOR**Mukesh Tiwari**

31-07-2025 13:02

CHECKER**Mukesh Tiwari**

Status: Completed

Remarks: Bulk PASS decision by CHECKER

31-07-2025 13:05

QUESTION	STATUS	ATTEMPT DETAILS
Check alignment	COMPLETED (3 attempts)	Attempt 1
		CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 31-07-2025 12:54
		Attempt 2
		MAKER Mukesh Tiwari Remarks: done 31-07-2025 12:55
		SUPERVISOR Mukesh Tiwari 31-07-2025 12:57
		CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor
		Attempt 3
		MAKER Mukesh Tiwari 31-07-2025 13:01
		SUPERVISOR Mukesh Tiwari 31-07-2025 13:02
		CHECKER Mukesh Tiwari Status: Completed Remarks: Bulk PASS decision by CHECKER 31-07-2025 13:05

QUESTION	STATUS	ATTEMPT DETAILS
Is the site clean?	COMPLETED (2 attempts)	Attempt 1
		CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 31-07-2025 12:54
		Attempt 2
		MAKER Mukesh Tiwari 31-07-2025 12:55
		SUPERVISOR Mukesh Tiwari 31-07-2025 12:58
		CHECKER Mukesh Tiwari Status: Completed Remarks: Bulk PASS decision by CHECKER 31-07-2025 13:05
Verify measurements	COMPLETED (2 attempts)	Attempt 1
		CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 31-07-2025 12:54

QUESTION	STATUS	ATTEMPT DETAILS
		Attempt 2
		MAKER Mukesh Tiwari 31-07-2025 12:55
		SUPERVISOR Mukesh Tiwari 31-07-2025 12:59
		CHECKER Mukesh Tiwari Status: Completed Remarks: Bulk PASS decision by CHECKER 31-07-2025 13:05
Is the paint uniform?	COMPLETED (3 attempts)	Attempt 1
		CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 31-07-2025 12:54
		Attempt 2
		MAKER Mukesh Tiwari 31-07-2025 12:55
		SUPERVISOR Mukesh Tiwari 31-07-2025 12:59
		CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor

QUESTION	STATUS	ATTEMPT DETAILS
		Attempt 3
		MAKER Mukesh Tiwari 31-07-2025 13:01
		SUPERVISOR Mukesh Tiwari 31-07-2025 13:03
		CHECKER Mukesh Tiwari Status: Completed Remarks: Bulk PASS decision by CHECKER 31-07-2025 13:05

Check for cracks	COMPLETED (2 attempts)	Attempt 1
		CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 31-07-2025 12:54

QUESTION	STATUS	ATTEMPT DETAILS
		Attempt 2
		MAKER Mukesh Tiwari 31-07-2025 12:55
		SUPERVISOR Mukesh Tiwari 31-07-2025 12:59
		CHECKER Mukesh Tiwari Status: Completed Remarks: Bulk PASS decision by CHECKER 31-07-2025 13:05
Are safety signs visible?	COMPLETED (3 attempts)	Attempt 1
		CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 31-07-2025 12:54
		Attempt 2
		MAKER Mukesh Tiwari 31-07-2025 12:55
		SUPERVISOR Mukesh Tiwari 31-07-2025 12:59
		CHECKER Mukesh Tiwari Status: Rejected_By_Supervisor

QUESTION	STATUS	ATTEMPT DETAILS
		Attempt 3
		MAKER Mukesh Tiwari 31-07-2025 13:01
		SUPERVISOR Mukesh Tiwari 31-07-2025 13:03
		CHECKER Mukesh Tiwari Status: Completed Remarks: Bulk PASS decision by CHECKER 31-07-2025 13:05

Is the wiring secured?	COMPLETED (2 attempts)	Attempt 1
		CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 31-07-2025 12:54

QUESTION	STATUS	ATTEMPT DETAILS
		Attempt 2
		MAKER Mukesh Tiwari 31-07-2025 12:55
		SUPERVISOR Mukesh Tiwari 31-07-2025 13:00
		CHECKER Mukesh Tiwari Status: Completed Remarks: Bulk PASS decision by CHECKER 31-07-2025 13:05

Check door operation	COMPLETED (2 attempts)	Attempt 1
		CHECKER Mukesh Tiwari Status: Rejected_By_Checker Remarks: Bulk FAIL decision by CHECKER 31-07-2025 12:54

QUESTION

STATUS

ATTEMPT DETAILS

Attempt 2

MAKER

Mukesh Tiwari

31-07-2025 12:55

SUPERVISOR

Mukesh Tiwari

31-07-2025 13:00

CHECKER

Mukesh Tiwari

Status: Completed

Remarks: Bulk PASS decision by CHECKER

31-07-2025 13:05