


Relatório GIMB

	TECSOIL AUTOMAÇÃO E SISTEMAS S/A CNPJ: 32.721.577/0001-89 - Inscr.: 177.439.998.114 AVENIDA BRASÍLIA, 2121, ANDAR 21 E 22 - NOVA IORQUE - CEP: 16018-000 - ARAÇATUBA - SP Telefone: (18) 3622-2270 - Site: www.solinftec.com	19919 21/02/2025
---	---	----------------------------

Dados do Serviço

Cliente: SLC - FAZENDA: PANTANAL

Razão social: SLC AGRÍCOLA S.A.

CPF/CNPJ: 0

Endereço: ROD. BR 060,

KM 4

Telefone: -

Realizado por: IGOR GONÇALO DIAS (IGOR.DIAS)

Atividade: REVISÃO/SUBSTITUIÇÃO DE INSTALAÇÕES

Tipo de equipamento: MÓDULO CLIMÁTICO

Equipamento: MÓDULO CLIMÁTICO / - **Identificador:** - / 0

Descrição detalhada da visita

Assunto	Frota	Situação	Ação
SENSORES DE CHUVA ESTRAGADOS			
CAIXA HERMÉTICA COM RACHADURAS DEVIDO A EXPOSIÇÃO AO TEMPO.			
TESTES REALIZADOS NO SENSOR 1			
TESTES REALIZADOS NO SENSOR 2			
TESTES REALIZADOS NO SENSOR 3			

Imagens



SENSORES DE CHUVA ESTRAGADOS



CAIXA HERMÉTICA COM RACHADURAS DEVIDO A EXPOSIÇÃO AO TEMPO.

Quick Test			General status	Done	Log
Quick tests					
Boot button	Waiting...	0.00 s			09:43:30.833 - Removal
3G/4G Module	Waiting...	0.00 s			09:43:42.943 - Detection COM - Microsoft Weather Station - Dispositivo Serial USB - Insertion
GPS Module	Waiting...	0.00 s			09:43:46.056 - Please tilt the rain gauge...
Radio 433 MHz (LPMAN) Module	Waiting...	0.00 s			09:43:46.144 - The rain gauge was tilted...
Temperature, humidity and pressure (RS485)	Waiting...	0.00 s			09:43:46.111 - Please tilt the rain gauge 8 times...
Anemometer (RS485 C0)	Waiting...	0.00 s			09:43:46.245 - The test of rain gauge has been timed out
Pyranometer (RS485 D0)	Waiting...	0.00 s			
Rain gauge	Timed out	38,289 s			
Solinftec soil moisture and leaf wetness	Waiting...	0.00 s			

TESTES REALIZADOS NO SENSOR 1

Quick Test			General status	Done	Log
Quick tests					
Boot button	Waiting...	0.00 s			09:43:40.772 - Removal
3G/4G Module	Waiting...	0.00 s			09:43:42.427 - Detection COM - Microsoft Weather Station - Dispositivo Serial USB - Insertion
GPS Module	Waiting...	0.00 s			09:43:46.147 - Sending AT to 3G/4G module...
Radio 433 MHz (LPMAN) Module	Waiting...	0.00 s			09:43:46.899 - Setting 3G/4G communication to CTS_HS_SERIAL_RAUMATE_440000
Temperature, humidity and pressure (RS485)	Waiting...	0.00 s			09:43:46.955 - Sending AT to 3G/4G module...
Anemometer (RS485 C0)	Waiting...	0.00 s			09:43:46.816 - Sending AT to 3G/4G module...
Pyranometer (RS485 D0)	Waiting...	0.00 s			09:43:46.878 - Sending AT to 3G/4G module...
Rain gauge	Timed out	38,144 s			09:43:47.141 - Sending AT to 3G/4G module...
Solinftec soil moisture and leaf wetness	Waiting...	0.00 s			09:43:46.283 - Sending AT to 3G/4G module...
					09:43:46.344 - Sending AT to 3G/4G module...
					09:43:46.429 - The 3G/4G test was aborted
					09:43:47.227 - Please tilt the rain gauge...
					09:43:46.756 - The rain gauge was tilted...
					09:43:46.747 - Please tilt the rain gauge 7 times...
					09:43:47.278 - The test of rain gauge has been timed out

TESTES REALIZADOS NO SENSOR 2

Quick Test			General status	Done	Log
Quick tests					
Boot button	Waiting...	0.00 s			09:43:46.611 - Removal
3G/4G Module	Waiting...	0.00 s			09:43:42.907 - Detection COM - Microsoft Weather Station - Dispositivo Serial USB - Insertion
GPS Module	Waiting...	0.00 s			09:43:46.808 - Please tilt the rain gauge...
Radio 433 MHz (LPMAN) Module	Waiting...	0.00 s			09:43:46.844 - The rain gauge was tilted...
Temperature, humidity and pressure (RS485)	Waiting...	0.00 s			09:43:46.111 - Please tilt the rain gauge 8 times...
Anemometer (RS485 C0)	Waiting...	0.00 s			09:43:46.245 - The test of rain gauge has been timed out
Pyranometer (RS485 D0)	Waiting...	0.00 s			09:43:46.267 - Please tilt the rain gauge...
Rain gauge	Timed out	38,152 s			09:43:46.406 - The test of rain gauge has been timed out
Solinftec soil moisture and leaf wetness	Waiting...	0.00 s			

TESTES REALIZADOS NO SENSOR 3