



Dept.	Technical reference	Created by Morten Nielsen	20-12-2017			Approved by
The 4x 2.5mm holes should be threaded m3		Document type	Document status			
		Title MotorShield Left	DWG No.			
			Rev.	Date of issue	Sheet 1/1	