



Dept.	Technical reference	Created by Morten Nielsen	20-12-2017		Approved by
The 4x 2.5mm holes should be threaded m3		Document type	Document status		
		Title MotorShield right	DWG No.		
		Rev.	Date of issue		Sheet 1/1