

Technical drawing of a circular part. The drawing shows a circle with a horizontal centerline. A vertical dimension line on the left indicates a distance of 5 from the centerline to the top edge. A horizontal dimension line at the top indicates a distance of 11,7 from the centerline to the right edge. A small circular detail is shown on the right side of the main circle, with a radius dimension of R0,5. A larger circular detail is shown on the left side of the main circle, with a radius dimension of R1. The drawing is a technical sketch of a mechanical part.